QUALITY CONTROL

BR No: 16 dt 30.4.2013.

Name of the Work: Reserve fund for Emergency works in Bagalagunte Road foot paths Drain Development works Improvements to Cross road to Nunnikondappa layout & Nunnetwara Nagara in W.No.14

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 2 years back.

Assistance Executive Engineer
Dasarahalli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike